


YEAR  
1989 - 90

MODEL  
LEGEND

VIN APPLICATION  
ALL

BULLETIN NO.  
93-019



## Product Update: Legend Igniter

### BACKGROUND

The igniter may fail. If this happens, the engine will not start. This product update is being conducted to help eliminate any possibility of igniter failure.



### CUSTOMER NOTIFICATION

Owners of affected vehicles will be contacted by mail and asked to take the car to a dealership for repair. The text of the customer letter is on the back of this service bulletin.


### CORRECTIVE ACTION

Replace the igniter with the updated part listed under PARTS INFORMATION.

1. Inspect the igniter mounted on the left inner fender panel.
  - If the mounting bolts go through the heat sink, it is not an updated igniter. Continue with this replacement procedure.
  - If the mounting bolts go through the igniter body, it is an updated igniter. Go to step 6.



2. Disconnect the 4-pin igniter connector.
3. Remove the igniter mounting bolts and the igniter. Discard the bolts and the igniter.
4. Connect the 4-pin connector to the new igniter.
5. Install the igniter with the new bolts that came in the kit. Torque the bolts to 10 N·m (1.0 kg·m, 7 lb-ft).
6. Center-punch a completion mark above the "H" in the engine compartment VIN.



### PARTS INFORMATION

Igniter Kit: P/N 06302-PL2-H00

### WARRANTY CLAIM INFORMATION

| Operation Number | Description                          | Flat Rate Time |
|------------------|--------------------------------------|----------------|
| 117535           | Inspect igniter only, no replacement | 0.2            |
| 117135           | Inspect and replace igniter          | 0.2            |

Failed P/N: 30120-PL2-014

Defect code: 625

Contention code: J73

September 1993

## Product Update: Legend Ignition System

Dear Legend Owner:

Honda Motor Co., Ltd. has determined that a part in your car's ignition system does not meet Acura's standards for durability. If this part, called the igniter, should fail, your car's engine will not start.

An improved igniter is now available. Please call your Acura dealer and schedule an appointment to have it installed. *This update will be done free of charge.* Please plan to leave your car at the dealer for at least half a day to allow him flexibility in scheduling.

*Even if you had the igniter replaced previously, you should have it replaced with the improved unit.* Please make an appointment with the dealer to have it installed. In addition, you are eligible for reimbursement if you paid for a previous igniter replacement. Reimbursement is subject to the eligibility requirements given on the enclosed "Request for Reimbursement" form included for your convenience.

We apologize for any inconvenience this product update may cause you; however, our main concern is the continued trouble-free operation of your Legend. If you have any questions, please call or write:

Acura Customer Relations Department  
1919 Torrance Boulevard  
Torrance, CA 90501-2746

(800) 382-2238

Sincerely,

**AMERICAN HONDA MOTOR CO., INC.**  
**Acura Automobile Division**